

George Mason & 9th St N (Phase 2)

Project Description: The project installed [Rectangular Rapid-Flashing Beacons \(RRFB\)](#), replaced the marked median with concrete, added curb ramp improvements on the southeast corner, and built out the marked curb extensions on the west side of the intersection. These changes help improve the existing school crossing to Escuela Key Elementary.

Safety Need: Identified through systemic analysis of uncontrolled crossings.

Before Treatment



After Treatment

