

WILLIAMSBURG BLVD & 36TH ST N

BEFORE TREATMENT



Safety Issue: Identified through the [school zone retrofits process](#)

Project Description: The project added tactical [curb extensions](#) (using markings and flex posts) to the northwest and southeast corners of the intersection, which shortened crossing distances for pedestrians and slowed vehicle turning speeds. It also added SLOW SCHOOL XING pavement markings in advance of the school zone crossing over arterial Williamsburg Blvd per the County's [school zone guidelines](#).

AFTER TREATMENT

