GULF BRANCH OUTFALL REPAIR

N Peary/N Piedmont Outfall

Summer 2025 Engagement









Outfall Area Current Conditions, Goals & Considerations

Current Conditions

- Actively Eroding, Damaged Outfall
- Endwall Undermined, Fell Into Stream Channel
- Invasive Bamboo Spreading

Project Goals

- Create a stable outfall
- Maintain the storm infrastructure, repair erosion
- Remove invasive plants, add native plants
- Minimize impacts to the stream corridor

Site-specific project considerations include maintaining the pedestrian bridge, bamboo removal, feasible access paths, protecting high-value habitat, and coordinating the approach with neighbors. Other thoughts?



Gulf Branch Outfall Repair

Arlington, Virginia March 2025








Gulf Branch Outfall Repair

Arlington, Virginia March 2025









Gulf Branch Outfall Repair

Arlington, Virginia March 2025









Draft conceptual design ONLY – to be refined via engineering analysis

- New survey data shows banks are higher than previous surveys showed.
- Design adjustments will be needed to prevent future erosion.
- Stacked stone and grading options were both considered.
- Grading would have more disturbance and higher tree impact.
- Stacked stone is preferred by project team to minimize impacts and provide more long-term stability.

Property Boundaries, Existing Easements, Proposed Temporary Easement



Property Boundaries, Existing Easements, Proposed Permanent Easement



Next Steps

- Develop draft final design, re-engage
 - Fall 2025 or Winter 2026
- Construction start timeline may depend on Gulf Branch stream project progress

Questions? Contact:

Ty Asfaw, Project Manager TAsfaw@arlingtonva.us

Lily Whitesell, Stormwater Engagement <u>LWhitesell@arlingtonva.us</u>