


WILSON BLVD & N QUINN ST

BEFORE TREATMENT



Safety Need: Identified through a project to resolve a drainage issue at the northeast corner of the intersection.

Project Description: This project installed a concrete valley gutter to improve stormwater drainage and provide new concrete islands to protect bike and pedestrians crossing at the northwest corner of the intersection where there is a protected bike lane connection.



AFTER TREATMENT

