

# N CLARENDON BLVD & N CLEVELAND ST

## BEFORE TREATMENT



**Safety Issue:** Identified through a community report.

**Project Description:** Improvements at this intersection included curb extensions at the NW and SW corners, and upgrading the ramps at the NW, SW, and SW corners to meet ADA standards.

## AFTER TREATMENT

