

# 10TH ST N & N BARTON ST

## BEFORE TREATMENT



**Safety Issue:** Identified through a community report.

**Project Description:** Improvements at this intersection included upgrading the ramp at the SW to meet ADA standards.

## AFTER TREATMENT

