

6th ST S & S ADAMS ST

BEFORE TREATMENT



Safety Issue: Identified through a community report.

Project Description: This project extended the existing median to provide a safer crossing for pedestrians.

AFTER TREATMENT

