

WASHINGTON BLVD & 4TH ST N

BEFORE TREATMENT



Safety Issue: Identified through the [Washington Blvd HIN Safety Audit](#).

Project Description: This project extended the existing median to provide a safer crossing for pedestrians.

AFTER TREATMENT

