


WILSON BLVD & N GARFIELD ST

BEFORE TREATMENT



Safety Issue: Identified through systemic safety analysis on the High-Injury Network.

Project Description: Improvements at the intersection included tactical, marked curb extensions with bollards to shorten crossing distances for pedestrians and slow vehicle turning speeds.

AFTER TREATMENT

