

# N Randolph St and 20<sup>th</sup> Rd N

## BEFORE TREATMENT



**Safety Issue:** The crosswalk leading to St. Agnes School was not marked or ADA accessible. Previously, there was a crosswalk on N Randolph St that led directly to a utility pole and did not have a curb ramp.

**Project Description:** This project improved accessibility by moving the crosswalk a few feet north to a location without any obstructions, installing a new curb ramp, and marking two new high visibility crosswalks. In addition, a school crossing sign was installed to increase visibility of pedestrians, especially children, crossing at this location.

**Completed:** October 2021

## AFTER TREATMENT

