

## OIPI GAP-TA Custis Trail

Existing Conditions Map Series  
Page Number Index



0 0.25 0.5 1 1.5 2 Miles

### Pavement Condition

- Excellent
- Good
- Fair
- Poor


### Bicycle Facility Type

- On Street Route
- Off Street Trail
- Planned On Street Route
- Planned Off Street Trail
- Recommended Route

DCGIS, Fairfax County, VA, VGIN, Esri, TomTom, Garmin, SafeGraph, GeoTechnologies, Inc, METI/NASA, USGS, EPA, NPS, US Census Bureau, USDA, USFWS, USFWS

Arlington National Cemetery

Joint Base Myer-Henderson Hall



## OIPI GAP-TA Custis Trail

Existing Conditions Map Series  
Page 1 of 24



0 50 100 200 300 400 Feet

### Issue Type

- Curb Ramp (1)
- Drainage/Ponding (1)
- Other Amenity (1)
- Pavement Condition (1)
- Signage/Wayfinding (3)

### Resource Protection Areas


Resource Protection Areas

### Pavement Condition

- Excellent
- Good
- Fair

### Bicycle Facility Type

- On Street Route
- Off Street Trail



## OIPI GAP-TA Custis Trail

Existing Conditions Map Series  
Page 2 of 24



0 50 100 200 300 400 Feet

### Issue Type


- Curb Ramp (2)
- Fixed Object (1)
- Lighting (3)

### Pavement Condition

- Excellent
- Fair

### Bicycle Facility Type

- On Street Route
- Off Street Trail
- Recommended Route




## OIPI GAP-TA Custis Trail

Existing Conditions Map Series  
Page 3 of 24



0 50 100 200 300 400 Feet



**OIPI GAP-TA Custis Trail**  
Existing Conditions Map Series  
Page 4 of 24



0 50 100 200 300 400 Feet

**Issue Type**


- Curb Ramp (2)
- Drainage/Ponding (2)
- Lighting (1)

**Pavement Condition**

- Pavement Condition (1)
- Signage/Wayfinding (2)
- Trail Width (1)

**Pavement Condition** **Bicycle Facility Type**

- Excellent
- Good
- Fair
- Off Street Trail
- Planned On Street Route



## OIPI GAP-TA Custis Trail

Existing Conditions Map Series  
Page 5 of 24

0 50 100 200 300 400 Feet



### Issue Type

- Curb Ramp (2)
- Drainage/Ponding (2)
- Fixed Object (1)
- Other Amenity (1)

### Resource Protection Areas




- Signage/Wayfinding (2)
- Trail Width (2)

### Pavement Condition

- Good

### Bicycle Facility Type

- On Street Route
- Off Street Trail



## OIPI GAP-TA Custis Trail

Existing Conditions Map Series  
Page 6 of 24



0 50 100 200 300 400 Feet

### Issue Type

- Curb Ramp (2)
- Drainage/Ponding (3)
- Dropoff/Sewer Grates (1)
- Fixed Object (1)
- Lighting (3)


### Resource Protection Areas

- Resource Protection Areas

### Pavement Condition

### Bicycle Facility Type

- Excellent
- Good
- Fair
- Off Street Trail



## OIPI GAP-TA Custis Trail

Existing Conditions Map Series  
Page 7 of 24

0 50 100 200 300 400 Feet



### Issue Type

- Curb Ramp (1)
- Drainage/Ponding (1)
- Lighting (2)
- Pavement Condition (1)
- Signage/Wayfinding (1)


### Resource Protection Areas

### Pavement Condition

- Fair

### Bicycle Facility Type

- On Street Route
- Off Street Trail
- - - Planned Off Street Trail



**OIPI GAP-TA Custis Trail**  
Existing Conditions Map Series  
Page 8 of 24

0 50 100 200 300 400 Feet



**Issue Type**

- Curb Ramp (2)
- Drainage/Ponding (1)
- Dropoff/Sewer Grates (4)
- Fixed Object (1)

**Pavement Condition**

- Lighting (3)
- Other Amenity (2)
- Pavement Condition (1)
- Signage/Wayfinding (2)
- Trail Width (1)
- Tree/Rooting (1)

**Resource Protection Areas**

Resource Protection Areas


**Bicycle Facility Type**

Off Street Trail

Planned On Street Route

Excellent

Good



**OIPI GAP-TA Custis Trail**  
Existing Conditions Map Series  
Page 9 of 24

0 50 100 200 300 400 Feet



#### Issue Type

- Curb Ramp (4)
- Dropoff/Sewer Grates (1)
- Fixed Object (1)
- Lighting (2)

#### Other Amenity (1)

- Pavement Condition (2)
- Signage/Wayfinding (4)
- Trail Width (1)
- Visibility/Blind Spots (2)

#### Other (2)

- On Street Route
- Planned On Street Route


#### Pavement Condition

#### Good

#### Fair

#### Poor

#### Bicycle Facility Type



**OIPI GAP-TA Custis Trail**  
Existing Conditions Map Series  
Page 10 of 24



0 50 100 200 300 400 Feet

**Issue Type**

- Curb Ramp (1)
- Pavement Condition (1)
- Steep Slope (2)


**Other (1)**

**Pavement Condition**

- Good
- Poor

**Bicycle Facility Type**

- On Street Route
- Planned On Street Route



**OIPI GAP-TA Custis Trail**  
Existing Conditions Map Series  
Page 11 of 24

0 50 100 200 300 400 Feet



**Issue Type**

- Dropoff/Sewer Grates (1)
- Lighting (1)
- Steep Slope (1)


- Trail Width (1)
- Tree/Rooting (1)
- Other (1)

**Pavement Condition**

Good

**Bicycle Facility Type**

On Street Route



## OIPI GAP-TA Custis Trail

Existing Conditions Map Series  
Page 12 of 24

0 50 100 200 300 400 Feet



### Issue Type

- Dropoff/Sewer Grates (2)
- Tree/Rooting (1)
- Other Amenity (1)
- Signage/Wayfinding (3)
- Steep Slope (2)

### Resource Protection Areas

Resource Protection Areas


### Pavement Condition

Good

### Bicycle Facility Type

On Street Route

Off Street Trail



**OIPI GAP-TA Custis Trail**  
Existing Conditions Map Series  
Page 13 of 24

0 50 100 200 300 400 Feet



#### Issue Type

- Dropoff/Sewer Grates (1)
- Lighting (1)
- Other Amenity (1)
- Signage/Wayfinding (3)
- Steep Slope (3)
- Trail Width (3)
- Tree/Rooting (1)
- Visibility/Blind Spots (1)
- Other (1)

#### Resource Protection Areas


- Resource Protection Areas (Red diagonal lines)

#### Pavement Condition

- Good (Green)
- Fair (Yellow)

#### Bicycle Facility Type

- On Street Route (Yellow line)
- Off Street Trail (Blue line)
- Planned On Street Route (Dashed Yellow line)



## OIPI GAP-TA Custis Trail

Existing Conditions Map Series  
Page 14 of 24

0 50 100 200 300 400 Feet



### Issue Type

- Trail Width (2)
- Tree/Rooting (1)
- Visibility/Blind Spots (2)

### Resource Protection Areas


- Resource Protection Areas

### Pavement Condition

- Good
- Fair

### Bicycle Facility Type

- On Street Route



## OIPI GAP-TA Custis Trail

Existing Conditions Map Series  
Page 15 of 24



0 50 100 200 300 400 Feet

### Issue Type


- Curb Ramp (2)
- Drainage/Ponding (1)
- Lighting (4)
- Steep Slope (3)
- Trail Width (4)
- Tree/Rooting (2)
- Visibility/Blind Spots (2)
- Other (1)

### Pavement Condition

- Good
- Fair

### Bicycle Facility Type

- On Street Route
- Planned On Street Route



## OIPI GAP-TA Custis Trail

Existing Conditions Map Series  
Page 16 of 24



0 50 100 200 300 400 Feet

### Issue Type

- Signage/Wayfinding (2)
- Trail Width (4)
- Other (1)

### Resource Protection Areas

- Resource Protection Areas

### Pavement Condition

- Good
- Fair

### Bicycle Facility Type

- Off Street Trail


- Planned On Street Route



OIPI GAP-TA Custis Trail  
Existing Conditions Map Series  
Page 17 of 24



- Other (1)
- Resource Protection Areas
- Resource Protection Areas
- Bicycle Facility Type
- On Street Route
- Off Street Trail
- Pavement Condition
- Good



## OIPI GAP-TA Custis Trail

## Existing Conditions Map Series



0 50 100 200 300 400 Feet

- Drainage/Ponding (2)
- Signage/Wayfinding (1)
- Steep Slope (1)
- Trail Width (3)


- Tree/Rooting (1)
- Other (1)

## Pavement Condition

— Goo

### **s Bicycle Facility Type**

## — Off Street Tra



## OIPI GAP-TA Custis Trail

Existing Conditions Map Series  
Page 19 of 24

0 50 100 200 300 400 Feet



**Issue Type**

- Drainage/Ponding (3)
- Lighting (1)
- Pavement Condition (1)
- Signage/Wayfinding (2)
- Steep Slope (1)

### Resource Protection Areas


Resource Protection Areas

### Pavement Condition

- Good
- Fair

### Bicycle Facility Type

Off Street Trail



## OIPI GAP-TA Custis Trail

Existing Conditions Map Series  
Page 20 of 24

0 50 100 200 300 400 Feet



### Issue Type

- Drainage/Ponding (3)
- Signage/Wayfinding (1)
- Trail Width (1)
- Tree/Rooting (1)
- Other (2)


### Pavement Condition

- Good
- Fair

### Bicycle Facility Type

- On Street Route
- Off Street Trail
- Planned On Street Route
- Planned Off Street Trail

● Capital Bikeshare Station



**OIPI GAP-TA Custis Trail**  
Existing Conditions Map Series  
Page 21 of 24

0 50 100 200 300 400  
Feet



#### Issue Type

- Curb Ramp (1)
- Fixed Object (1)
- Other Amenity (2)
- Signage/Wayfinding (3)

#### Pavement Condition


- Good (Green line)
- Planned On Street Route (Dashed orange line)
- Capital Bikeshare Station (Yellow icon)

#### Resource Protection Areas

- Resource Protection Areas (Red hatched area)

#### Bicycle Facility Type

- On Street Route (Yellow line)
- Off Street Trail (Blue line)



## OIPI GAP-TA Custis Trail

Existing Conditions Map Series  
Page 22 of 24



0 50 100 200 300 400  
Feet

### Issue Type

- Lighting (1)
- Other Amenity (2)
- Signage/Wayfinding (2)

### Issue Type


- Trail Width (4)
- Tree/Rooting (1)
- Visibility/Blind Spots (3)
- Other (1)

### Pavement Condition

- Good
- Fair

### Bicycle Facility Type

- On Street Route
- Planned On Street Route
- Capital Bikeshare Station



## OIPI GAP-TA Custis Trail

Existing Conditions Map Series  
Page 23 of 24



0 50 100 200 300 400 Feet

### Issue Type

- Fixed Object (2)
- Lighting (1)
- Other Amenity (1)
- Signage/Wayfinding (1)
- Steep Slope (1)

### Resource Protection Areas


- Resource Protection Areas

### Pavement Condition

- Excellent
- Fair

### Bicycle Facility Type

- Planned On Street Route



## OIPI GAP-TA Custis Trail

Existing Conditions Map Series  
Page 24 of 24



0 50 100 200 300 400 Feet

### Issue Type

- Trail Width (1)
- Visibility/Blind Spots (1)

### Pavement Condition

- Excellent

### Bicycle Facility Type

- On Street Route
- Off Street Trail
- Planned On Street Route