

OIPI GAP-TA Custis Trail
Public Comment Map Series
Page 2 of 24

0 50 100 200 300 400 Feet




Segment

- 1 - Bon Air Park
- 2 - Bluemont
- 3 - Waycroft-Woodlawn
- 4 - Waverly Hills

Issue Type

- Curb Ramp
- Drainage/Ponding
- Dropoff/Sewer Grates
- Fixed Object
- Lighting
- Other Amenity
- Pavement Condition
- Signage/Wayfinding
- Steep Slope
- Tree/Rooting
- Visibility/Blind Spots
- Other



OIPI GAP-TA Custis Trail
Public Comment Map Series
Page 3 of 24

0 50 100 200 300 400 Feet




Segment

- 1 - Bon Air Park
- 2 - Bluemont
- 3 - Waycroft-Woodlawn
- 4 - Waverly Hills

Issue Type

- Curb Ramp
- Drainage/Ponding
- Pavement Condition
- Dropoff/Sewer Grates
- Signage/Wayfinding
- Steep Slope
- Tree/Rooting
- Visibility/Blind Spots
- Other



OIPI GAP-TA Custis Trail
Public Comment Map Series
Page 4 of 24

0 50 100 200 300 400 Feet



Segment


- 1 - Bon Air Park
- 2 - Bluemont
- 3 - Waycroft-Woodlawn
- 4 - Waverly Hills

Issue Type

- Curb Ramp
- Drainage/Ponding
- Dropoff/Sewer Grates
- Fixed Object

Issue Type

- Tree/Rooting
- Visibility/Blind Spots
- Other



OIPI GAP-TA Custis Trail

Public Comment Map Series

Page 5 of 24

0 50 100 200 300 400 Feet




Segment

- 1 - Bon Air Park
- 2 - Bluemont
- 3 - Waycroft-Woodlawn
- 4 - Waverly Hills

Issue Type

- Curb Ramp
- Drainage/Ponding
- Dropoff/Sewer Grates
- Fixed Object
- Lighting
- Other Amenity
- Pavement Condition
- Signage/Wayfinding
- Steep Slope
- Tree/Rooting
- Visibility/Blind Spots
- Other



OIPI GAP-TA Custis Trail
Public Comment Map Series
Page 6 of 24

0 50 100 200 300 400 Feet



Segment

- 1 - Bon Air Park
- 2 - Bluemont
- 3 - Waycroft-Woodlawn
- 4 - Waverly Hills

Issue Type

- Curb Ramp
- Drainage/Ponding
- Dropoff/Sewer Grates
- Fixed Object

- Lighting
- Other Amenity
- Pavement Condition
- Signage/Wayfinding
- Steep Slope
- Tree/Rooting
- Visibility/Blind Spots
- Other



OIPI GAP-TA Custis Trail
Public Comment Map Series
Page 7 of 24

0 50 100 200 300 400 Feet




Segment

- 1 - Bon Air Park
- 2 - Bluemont
- 3 - Waycroft-Woodlawn
- 4 - Waverly Hills

Issue Type

- Lighting
- Curb Ramp
- Other Amenity
- Drainage/Ponding
- Pavement Condition
- Dropoff/Sewer Grates
- Signage/Wayfinding
- Steep Slope
- Tree/Rooting
- Visibility/Blind Spots
- Other
- Fixed Object
- Trail Width



OIPI GAP-TA Custis Trail
Public Comment Map Series
Page 8 of 24

0 50 100 200 300 400 Feet




Segment

- 1 - Bon Air Park
- 2 - Bluemont
- 3 - Waycroft-Woodlawn
- 4 - Waverly Hills

5 - Cherry Valley Park
6 - Thrifton Hill Park
7 - Spout Run
8 - North Highlands
9 - Rosslyn

Issue Type

- Lighting
- Curb Ramp
- Drainage/Ponding
- Dropoff/Sewer Grates
- Fixed Object
- Other
- Tree/Rooting
- Visibility/Blind Spots
- Other



OIPI GAP-TA Custis Trail

Public Comment Map Series

Page 9 of 24

0 50 100 200 300 400 Feet



Segment


- 1 - Bon Air Park
- 2 - Bluemont
- 3 - Waycroft-Woodlawn
- 4 - Waverly Hills

- 5 - Cherry Valley Park
- 6 - Thrifton Hill Park
- 7 - Spout Run
- 8 - North Highlands
- 9 - Rosslyn

Issue Type

- Curb Ramp
- Drainage/Ponding
- Dropoff/Sewer Grates
- Fixed Object

- Lighting
- Other Amenity
- Pavement Condition
- Signage/Wayfinding
- Steep Slope
- Tree/Rooting
- Visibility/Blind Spots
- Other



OIPI GAP-TA Custis Trail

Public Comment Map Series

Page 10 of 24

0 50 100 200 300 400 Feet



Segment

- 1 - Bon Air Park
- 2 - Bluemont
- 3 - Waycroft-Woodlawn
- 4 - Waverly Hills

- 5 - Cherry Valley Park
- 6 - Thrifton Hill Park
- 7 - Spout Run
- 8 - North Highlands
- 9 - Rosslyn

Issue Type

- Curb Ramp
- Drainage/Ponding
- Dropoff/Sewer Grates
- Fixed Object

- Lighting
- Other Amenity
- Pavement Condition
- Signage/Wayfinding
- Steep Slope
- Tree/Rooting
- Visibility/Blind Spots
- Other



OIPI GAP-TA Custis Trail
Public Comment Map Series
Page 11 of 24

0 50 100 200 300 400 Feet



Segment

- 1 - Bon Air Park
- 2 - Bluemont
- 3 - Waycroft-Woodlawn
- 4 - Waverly Hills


- 5 - Cherry Valley Park
- 6 - Thrifton Hill Park
- 7 - Spout Run
- 8 - North Highlands
- 9 - Rosslyn

Issue Type

- Curb Ramp
- Drainage/Ponding
- Dropoff/Sewer Grates
- Fixed Object

Issue Type

- Lighting
- Other Amenity
- Pavement Condition
- Signage/Wayfinding
- Steep Slope
- Tree/Rooting
- Visibility/Blind Spots
- Other



OIPI GAP-TA Custis Trail

Public Comment Map Series
Page 12 of 24

0 50 100 200 300 400 Feet



Segment


- 1 - Bon Air Park
- 2 - Bluemont
- 3 - Waycroft-Woodlawn
- 4 - Waverly Hills

Segment

- 5 - Cherry Valley Park
- 6 - Thrifton Hill Park
- 7 - Spout Run
- 8 - North Highlands
- 9 - Rosslyn

Issue Type

- Curb Ramp
- Drainage/Ponding
- Dropoff/Sewer Grates
- Fixed Object
- Lighting
- Other Amenity
- Pavement Condition
- Signage/Wayfinding
- Steep Slope
- Tree/Rooting
- Visibility/Blind Spots
- Other



OIPI GAP-TA Custis Trail
Public Comment Map Series
Page 13 of 24

0 50 100 200 300 400 Feet



Segment

- 1 - Bon Air Park
- 2 - Bluemont
- 3 - Waycroft-Woodlawn
- 4 - Waverly Hills
- 5 - Cherry Valley Park
- 6 - Thrifton Hill Park
- 7 - Spout Run
- 8 - North Highlands
- 9 - Rosslyn

Issue Type

- Curb Ramp
- Drainage/Ponding
- Pavement Condition
- Dropoff/Sewer Grates
- Signage/Wayfinding
- Steep Slope
- Tree/Rooting
- Visibility/Blind Spots
- Other
- Fixed Object
- Trail Width



OIPI GAP-TA Custis Trail
Public Comment Map Series
Page 14 of 24

0 50 100 200 300 400 Feet




Segment

- 1 - Bon Air Park
- 2 - Bluemont
- 3 - Waycroft-Woodlawn
- 4 - Waverly Hills
- 5 - Cherry Valley Park
- 6 - Thrifton Hill Park
- 7 - Spout Run
- 8 - North Highlands
- 9 - Rosslyn

Issue Type

- Curb Ramp
- Drainage/Ponding
- Pavement Condition
- Dropoff/Sewer Grates
- Signage/Wayfinding
- Steep Slope
- Tree/Rooting
- Visibility/Blind Spots
- Other



OIPI GAP-TA Custis Trail

Public Comment Map Series

Page 15 of 24



Fee

Segment

- 1 - Bon Air Park
- 2 - Bluemont
- 3 - Waycroft-Woodlawn
- 4 - Waverly Hills

5 - Cherry Valley Park

6 - Thrifton Hill Park

7 - Spout Run

8 - North Highlands

9 - Rosslyn

Issue Type

- Curb Ramp
- Drainage/Ponding
- Dropoff/Sewer Grates
- Fixed Object

● Lighting

- Other Amenity

- Pavement Condition


- Signage/Wayfin

- Steep Slope

● Tree/Rooting

- Visibility/Blind Spots

● Other



OIPI GAP-TA Custis Trail
Public Comment Map Series
Page 16 of 24

0 50 100 200 300 400 Feet




Segment

- 1 - Bon Air Park
- 2 - Bluemont
- 3 - Waycroft-Woodlawn
- 4 - Waverly Hills

Issue Type

- 5 - Cherry Valley Park
- 6 - Thrifton Hill Park
- 7 - Spout Run
- 8 - North Highlands
- 9 - Rosslyn
- Curb Ramp
- Other Amenity
- Drainage/Ponding
- Dropoff/Sewer Grates
- Fixed Object
- Lighting
- Other
- Tree/Rooting
- Visibility/Blind Spots
- Pavement Condition
- Signage/Wayfinding
- Steep Slope
- Trail Width



OIPI GAP-TA Custis Trail
Public Comment Map Series
Page 17 of 24

0 50 100 200 300 400 Feet




Segment

- 1 - Bon Air Park
- 2 - Bluemont
- 3 - Waycroft-Woodlawn
- 4 - Waverly Hills

Issue Type

- Curb Ramp
- Drainage/Ponding
- Dropoff/Sewer Grates
- Fixed Object
- Lighting
- Other Amenity
- Pavement Condition
- Signage/Wayfinding
- Steep Slope
- Tree/Rooting
- Visibility/Blind Spots
- Other



OIPI GAP-TA Custis Trail
Public Comment Map Series
Page 18 of 24

0 50 100 200 300 400 Feet




Segment

- 1 - Bon Air Park
- 2 - Bluemont
- 3 - Waycroft-Woodlawn
- 4 - Waverly Hills
- 5 - Cherry Valley Park
- 6 - Thrifton Hill Park
- 7 - Spout Run
- 8 - North Highlands
- 9 - Rosslyn

Issue Type

- Curb Ramp
- Drainage/Ponding
- Dropoff/Sewer Grates
- Fixed Object
- Lighting
- Other Amenity
- Pavement Condition
- Signage/Wayfinding
- Steep Slope
- Trail Width
- Tree/Rooting
- Visibility/Blind Spots
- Other



OIPI GAP-TA Custis Trail
Public Comment Map Series
Page 19 of 24

0 50 100 200 300 400 Feet




Segment

- 1 - Bon Air Park
- 2 - Bluemont
- 3 - Waycroft-Woodlawn
- 4 - Waverly Hills
- 5 - Cherry Valley Park
- 6 - Thrifton Hill Park
- 7 - Spout Run
- 8 - North Highlands
- 9 - Rosslyn

Issue Type

- Curb Ramp
- Dropoff/Sewer Grates
- Fixed Object
- Lighting
- Other Amenity
- Drainage/Ponding
- Signage/Wayfinding
- Steep Slope
- Tree/Rooting
- Visibility/Blind Spots
- Other



OIPI GAP-TA Custis Trail

Public Comment Map Series

Page 20 of 24

0 50 100 200 300 400 Feet




Segment

- 1 - Bon Air Park
- 2 - Bluemont
- 3 - Waycroft-Woodlawn
- 4 - Waverly Hills
- 5 - Cherry Valley Park
- 6 - Thrifton Hill Park
- 7 - Spout Run
- 8 - North Highlands
- 9 - Rosslyn

Issue Type

- Curb Ramp
- Drainage/Ponding
- Dropoff/Sewer Grates
- Fixed Object
- Lighting
- Other Amenity
- Pavement Condition
- Signage/Wayfinding
- Steep Slope
- Tree/Rooting
- Visibility/Blind Spots
- Other



OIPI GAP-TA Custis Trail
Public Comment Map Series
Page 21 of 24

0 50 100 200 300 400 Feet




Segment

- 1 - Bon Air Park
- 2 - Bluemont
- 3 - Waycroft-Woodlawn
- 4 - Waverly Hills

Issue Type

- Curb Ramp
- Drainage/Ponding
- Pavement Condition
- Dropoff/Sewer Grates
- Signage/Wayfinding
- Fixed Object
- Steep Slope
- Tree/Rooting
- Visibility/Blind Spots
- Other



OIPI GAP-TA Custis Trail

Public Comment Map Series

Page 22 of 24



Fee

Segment

- 1 - Bon Air Park
- 2 - Bluemont
- 3 - Waycroft-Woodlawn
- 4 - Waverly Hills

5 - Cherry Valley Park


- 6 - Thrifton Hill Park
- 7 - Spout Run
- 8 - North Highlands
- 9 - Rosslyn

Issue Type

- Curb Ramp
- Drainage/Ponding
- Dropoff/Sewer Grates
- Fixed Object

unting

- Visibility/Blind Spots
- Other



OIPI GAP-TA Custis Trail
Public Comment Map Series
Page 23 of 24

0 50 100 200 300 400 Feet



Segment

- 1 - Bon Air Park
- 2 - Bluemont
- 3 - Waycroft-Woodlawn
- 4 - Waverly Hills
- 5 - Cherry Valley Park
- 6 - Thrifton Hill Park
- 7 - Spout Run
- 8 - North Highlands
- 9 - Rosslyn

Issue Type

- Curb Ramp
- Drainage/Ponding
- Dropoff/Sewer Grates
- Fixed Object
- Lighting
- Other Amenity
- Pavement Condition
- Signage/Wayfinding
- Steep Slope
- Tree/Rooting
- Visibility/Blind Spots
- Other



OIPI GAP-TA Custis Trail
Public Comment Map Series
Page 24 of 24

0 50 100 200 300 400 Feet



Segment

- 1 - Bon Air Park
- 2 - Bluemont
- 3 - Waycroft-Woodlawn
- 4 - Waverly Hills
- 5 - Cherry Valley Park
- 6 - Thrifton Hill Park
- 7 - Spout Run
- 8 - North Highlands
- 9 - Rosslyn

Issue Type

- Lighting
- Curb Ramp
- Drainage/Ponding
- Dropoff/Sewer Grates
- Fixed Object
- Other Amenity
- Pavement Condition
- Signage/Wayfinding
- Steep Slope
- Tree/Rooting
- Visibility/Blind Spots
- Other