

Little Falls Rd – John Marshall Dr to N Kensington St

BEFORE TREATMENT – At John Marshall Dr & Little Falls Rd Intersection



Safety Issue: Project identified through critical crash response in 2022.

Project Description: (1) Improvements at John Marshall Dr include addition of a high visibility crosswalk on the south crosswalk, tactical curb extensions to sharpen/slow down turning vehicle turns and reduce crossing distances, and additional signage.

(2) Improvements at N Lexington St include bus stop/sharrow markings, high visibility crosswalks, and a tactical curb extension to sharpen/slow down turning vehicle turns and reduce crossing distances. (3) Improvements at N Kensington St (north side) include high visibility crosswalks, tactical curb extensions to sharpen/slow down turning vehicle turns and reduce crossing distances, and enhanced signage at the crossing over Little Falls Rd, as well as changing the yield to a stop sign (south side). [Click here to see the plan.](#)

Completed: December 2022

AFTER TREATMENT – At John Marshall Dr & Little Falls Rd Intersection

