



# Collisions Before and After: N Quincy St & 10<sup>th</sup> St N

In July 2019, the County installed safety modifications at the intersection of N Quincy St and 10<sup>th</sup> St N. Improvements include enhancing the median refuge, markings, and lighting conditions along N Quincy St. **The average number of collisions per year decreased from 2 in 2014-2019 (before project) to .67 in 2020-2022 (after project).**


### Collision Severity



### Collision Type



### Collision Characteristics



## Tools Implemented

### Crossing Signs & Markings



Alert drivers to expect pedestrians crossing and indicate preferred crossing locations for pedestrians.

### Lighting



Increase visibility for all road users, especially at crossings.

## Total Collisions

